

Airport Coordination Limited

The Airports Slot Allocation Regulation 2006

Notice of Financial Penalty to be paid by

Jet2 for repeatedly and intentionally operating without an allocated slot on 14 November 2009

16 December 2009

Airport Coordination Limited (ACL), as the appointed coordinator for Manchester Airport has the responsibility, inter alia, for the administration of the Misuse of Slots Enforcement Code 2007 (the Code), implemented at coordinated airports in the UK on 1 January 2007 in accordance with the Airport Slot Allocation Regulations 2006 (the UK Regulations).

ACL gave Jet2 a Notice of Final Decision on 4 December 2009 which notified Jet2 that pursuant to Regulation 16 of the UK Regulations, ACL had decided to impose a financial penalty on Jet2 in respect of repeated and intentional breaches of regulation 14 of the UK Regulations which occurred on 14 November 2009.

Accordingly, having agreed with Jet2 the facts and matters relied upon, ACL has imposed a financial penalty on Jet2 in the amount of £1,000.

Jet2 is aware that further operations without an allocated slot may result in further financial penalties being applied.

For more information concerning this matter generally, you should contact Tracey Buckmaster (direct line: 020 8564 0626 or email: sanctions@acl-uk.org).